


Calibration Instructions for Cobra Joystick V6

1. Press and hold the MODE button to plug the USB into the computer. At this time, the two lights are on, indicating that the software upgrade mode is entered.



The game controller display interface of computer as follows:



2. Short press the "START" button. At this time, the red light is on, indicating that the joystick calibration mode is entered. Then, rotate the X/Y axis, RZ axis, and THROTTLE axis to rotate a few turns (NOTE: do not use too much force when shaking).



3. Short press the "START" button. At this time, the green light is on which means that the joystick is calibrated and the software is automatically reset.



The game controller display interface of computer as follows:

